




00283988

RECEIVED

NOV 25 1968

R. 56 W

COLO. OIL & GAS CONS. COMM.



T.
12
N

Scale... 1" = 1000'

Powers Elevation Company, Inc. of Denver, Colorado
 has in accordance with a request from Warren Arnold
 for Chancellor Exploration & Exeter Drilling
 determined the location of No.1-X Duockowskyj
 to be 50'W & 80'S of C NW SW Section 23 Township 12 North
 Range 56 West of the ~~6th~~ 6th Principal Meridian
 Weld County, Colorado

I hereby certify that this plot is an
 accurate representation of a correct
 survey showing the location of

Date: 11-19-68


Bruce G. Halloran
 Licensed Land Surveyor No. 2853
 State of Colorado

05-123-7069

VP 6/1/88



VERBAL REQUEST



NOTICE OF INTENT TO DRILL _____

NOTICE OF INTENT TO ABANDON X EX. PROD.

OTHER _____

COMPANY Don Gregory

ADDRESS 115 W. 2ND KIMBAL, NE 69145

BY Bob Abramson

PHONE NO. _____ EXT. _____

WELL NO. 1-X

LEASE BUCKROWSKY

COUNTY WELD

FIELD SLEEPER

DRLG UNIT _____

LOCATION NWSW SEC 23 TWP 12N RNGE 56W MERIDIAN 6

1900 ft. from N or (S) Sec. Line, and 610 ft. from E or (W) Sec. Line

ESTIMATED DATE OF WORK N/A ESTIMATED TIME _____

DETAILS OF PLAN OF WORK: T.D. 6386 FORMATION SKULL CREEK

SURFACE CASING 8 5/8 @ 358, 5 1/2 @ 6383 Perfs 6318-22
CIBP @ 6310 & 6260 Perfs 6186-90

- ① PLACE SAND FROM 6260 - 6075 + 55x CEMENT OR/ SET
CIBP + 25x @ 6075 ± OR/ SET 105x CEMENT FROM 6140-6200
- ② Cut & Pull 5 1/2 @ FREEPOINT ③ PLACE 50 FT PLUG FROM
750 - 800 ④ PLACE 25 5x @ 358 1/2 IN, 1/2 OUT OF CASING
SHOE ⑤ PLACE 5 5x IN TOP OF CASING ⑥ CUT OFF 4' BELOW GROUND

BONDING STATUS: PLUGGING _____ SURFACE _____ OTHER & WELD ON PLATE

Is surface owner also mineral owner? _____

ACREAGE LEASED SURROUNDING DRILLSITE _____

X APPROVED BY: Mahat L. Vachil

DATE JUNE 1, 1988

STATE OF COLORADO
OIL AND GAS CONSERVATION COMMISSION
Department of Natural Resources
Suite 380, Logan Tower Building
1580 Logan Street
Denver, Colorado 80203

Lease
Field
County
Location


Gentlemen:

An inspection was made of the lease(s) shown above. The following conditions were observed to exist at the time of the inspection:

- Oil accumulation on the water in the retaining pit.
- Skim pit in need or repairs.
- Skim pit or tank should be constructed.
- No. I.D. number on tank.

Remarks: _____

The above condition(s) should be corrected immediately. Any surface accumulation of oil in the retaining pits must be cleaned off within ten (10) days after receipt of this notice (Rule 328), and a report submitted to this office within thirty (30) days after the work was accomplished, advising us of the date and manner in which the correction was made. Any person who fails to comply with this request is in violation of this Commission's Rules and Regulations and is subject to the penalties as provided for under 34-6-121 of the Oil and Gas Conservation Act.



William R. Smith, Director

NW 5w 23-12N-56w 1-X BUGZKOWSKYJ




BOB ABRAHAMSON
115 W. Second
2ND

Kinsow NE 69145

NW SW 23-12-56w



BUCZKOWSKYJ
59169 LN



Weld County

SLEEPER FIELD

Don GREGORY #35750

Pure CASING