



Third base 42-29



PW pipe was extended to reach pit





Controlled and contained spills/releases. Conduct maintenance on equipment, cleanup stained material and review self-inspection processes. To comply with 1003 Interim





Fence around pit has been repaired per Rule 1002.a.





Fence around pit has been repaired