

Cougar 42-14







Installed appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1),  
(2).