

**EVERGREEN NATURAL RESOURCES
SPILL / RELEASE RESPONSE FORM**

Spill/Release Point
Name & Number Barito Federal 31-24

Cause of Spill: Broken valve on wellhead

Discovered By: Gerald Garcia

Investigated By: T.J. Fernandez

Isolated By: Gerald Garcia

Was Spill Contained
Within Berm? YES / ☒ NO Weather
Conditions: Sunny, 59°, Calm

Date & Time of Incident: 1-7-22 1400

Facility Type: ☒ Well / Tank / Gathering / Pit / Other: _____

Estimated BBLs:	Water	Oil	Other:
	46		
BBLs Recovered:	5		

Depth of Impact: 3 in

Approximate Length & Width of Spill: L 207 ft W S ft

Description of Photos/Other Notes (Number photos and place number on drawing.)	
1. Source @ Wellhead	
2. Broken valve on wellhead gathering line	
3. Spill path facing east from source	
4. End of spill facing west toward source (East flow)	
5. Spill path facing west from source	
6. Spill path facing South @ Change of direction	
7. Spill path @ 2nd change of dir facing SE	
8. End of spill facing NE toward change of dir.	
9. Well placard	

Related Coordinates		
Lat / Long		
Start:	37.24953	-104.73174
Change of dir.	37.24945	-104.73197
Change of dir.	37.24934	-104.73193
End 1	37.24958	-104.73158
End 2	37.24922	-104.73165

Were any of the following impacted?	
Waters of the State	Yes / <input checked="" type="radio"/> No
Residence/Occupied Structure	Yes / <input checked="" type="radio"/> No
Surface Water Supply Area	Yes / <input checked="" type="radio"/> No
Public Byway	Yes / <input checked="" type="radio"/> No
Livestock	Yes / <input checked="" type="radio"/> No

