

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402925249

Date Received:
01/13/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Romana Cowden

720-951-5895

cogcc.inspections@caerusoilandgas.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696203223

Inspection Date: 10/13/2021

FIR Submit Date: 10/15/2021

FIR Status: _____

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 334156

Location Name: Shideler Fee Number: 31-13C (O31E) County: _____

Qtrqtr: SWSE Sec: 31 Twp: 7S Range: 92W Meridian: 6

Latitude: 39.396389 Longitude: -107.706410

FACILITY - API Number: 05-045-00 Facility ID: 334156

Facility Name: Shideler Fee Number: 31-13C (O31E)

Qtrqtr: SWSE Sec: 31 Twp: 7S Range: 92W Meridian: 6

Latitude: 39.396389 Longitude: -107.706410

CORRECTIVE ACTIONS:

1 CA# 156888

Corrective Action: Install wildlife screen per Rule 608.b.(7).

Date: 11/15/2021

Response: CA COMPLETED

Date of Completion: 11/04/2021

Operator Comment: Bird screen was installed.

COGCC Decision: _____

COGCC
Representative:

2 CA# 156889

Corrective Action: Comply with Rule 1002.c, 1002.f and 1003; Implement BMPs to protect soil stockpile from erosion degradation and to prevent weed establishment, and conduct additional reclamation at stockpile.

Date: 11/30/2021

Response: CA COMPLETED

Date of Completion: 11/04/2021

Operator
Comment: Raked and seeded stockpiles

COGCC Decision:

COGCC
Representative:

3 CA# 156890

Corrective Action: Install or repair BMPs following good engineering practices in accordance with Rule 1002.f.

Date: 10/22/2021

Response: CA COMPLETED

Date of Completion: 11/04/2021

Operator
Comment: Raked and seeded soil stockpiles, repaired BMP inlets and raked and seeded erosion.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Romana Cowden

Signed:

Title: EHS

Date: 1/13/2022 10:06:03 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
-----------------	-------------

--	--

Total Attach: 0 Files