

Mesa 43-20



Installed and repaired required BMPs per Rule 1002.f.(2)C



Installed and repaired required BMPs per Rule 1002.f.(2)C



Installed and repaired required BMPs per Rule 1002.f.(2)C

Rule 1002.e. Restrict access by fencing from the CR 51 to the metal building per landowner specification cannot be completed because we cannot confirm who has been parking there.

Attached R.O.W