

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402925239

Date Received:  
01/13/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Romana Cowden</u>	<u>720-951-5895</u>	<u>cogcc.inspections@caerusoilandgas.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696203219

Inspection Date: 10/13/2021 FIR Submit Date: 10/15/2021 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 334283

Location Name: SHIDELER-67S92W Number: 31SENE County: \_\_\_\_\_

Qtrqr: SENE Sec: 31 Twp: 7S Range: 92W Meridian: 6

Latitude: 39.405970 Longitude: -107.699480

FACILITY - API Number: 05-045-00 Facility ID: 334283

Facility Name: SHIDELER-67S92W Number: 31SENE

Qtrqr: SENE Sec: 31 Twp: 7S Range: 92W Meridian: 6

Latitude: 39.405970 Longitude: -107.699480

CORRECTIVE ACTIONS:

1  CA# 156886

Corrective Action: Comply with 1003 Rules; conduct additional reclamation on bare areas of the cut slope. Continue to monitor and manage interim areas until Location receives a passing final inspection.

Date: 11/30/2021

Response: CA COMPLETED Date of Completion: 11/02/2021

Operator Comment: Erosion down fill slope repaired, raked, and seeded.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. Operator has provided no documentation attached to this resolution to show work has been conducted per corrective action(s). A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

2  CA# 156887

Corrective Action: Comply with Rule 1002.f; implement temporary stormwater and erosion control measures until additional reclamation activities are performed at fill slope; at which point control measures to stabilize and protect the seeded soils will be required.

Date: 10/22/2021

Response: CA COMPLETED

Date of Completion: 11/02/2021

Operator Comment: Erosion repaired, raked, and seeded.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. Operator has provided no documentation attached to this resolution to show work has been conducted per corrective action(s). A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Romana Cowden

Signed: \_\_\_\_\_

Title: EHS

Date: 1/13/2022 9:54:26 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402925239	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files