

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS /SG 33-32

Location ID: 413524



Photo #5806 from entrance to location.



Photo #5805 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS /SG 33-32

Location ID: 413524



Photo #5807 Access road lacks stabilization.



Photo #5804 Insufficient tracking BMP located at entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS /SG 33-32

Location ID: 413524




Photo #5809 Insufficient tracking BMP at entrance to location.



Photo #5810 Tracking occurring on to highway 6.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS /SG 33-32

Location ID: 413524



Photo #5811 Tracking occurring from access road on to highway 6.



Photo #5812 Tracking occurring from access road for approximately 100 yards.