

VP → PA

Please Update WM



File

COLORADO OIL & GAS CONSERVATION COMMISSION FIELD INSPECTION REPORT

<input type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION <input checked="" type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100	
API No. 05- 075 - 06500		LEASE NAME: Kirk A-2	
LOCATION: NW SW 17-9N-53		OPERATOR: Trioka	
DATE: 8-22-95		INSPECTOR: Ed Binkley	
Insp. Type: CH	Insp. Status: PA	PA: Y <input checked="" type="radio"/> N <input type="radio"/>	Pass/Fail: P <input checked="" type="radio"/> F <input type="radio"/> Viol.: Y <input checked="" type="radio"/> N <input type="radio"/> NOV: Y <input checked="" type="radio"/> N <input type="radio"/>

INSPECTION ITEM

Travel 7-8
8 AM - 2 PM

COMMENTS

INPUT

Well ID Signs (Rule 210)	Observed plugging operation	
Pits (Reserve/Production) (Rule 902, 903, 904)	Trioka rig on site with	
Fences (Rule 604.C.(3), 1003.A)	Cementers, Inc. Good job	
Tank Battery Equipment (Rule 604)	CIBP w/ 5 sk, 50 sk @ 800'	
Fire Walls/Berms/Dikes (Rule 604)	40 sk @ 230', 10 sk @ 40'	
General Housekeeping (Rule 603.G)		
Spills (Oil/Water) (Rule 908)		
Bradenhead (Rule 207)		
Drilling Well/Workover (Rule 315)		
Surface Rehabilitation (Rule 317)		
Miscellaneous	Cement fell when top plug installed Re cement top plug w/ 10 sk.	

**CORRECTIVE ACTION REQUIRED:**

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.