

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402945658

Date Received:

02/02/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Trujillo, Aaron

aaron.trujillo@state.co.us

TEP

970-285-9377

COGCCInspectionReports@terraep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 700703783

Inspection Date: 01/26/2022

FIR Submit Date: 01/31/2022

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 323961

Location Name: CLOUGH-66S94W Number: 20SENE County: _____

Qtrqtr: SENE Sec: 20 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.511289 Longitude: -107.904530

FACILITY - API Number: 05-045-00 Facility ID: 323961

Facility Name: CLOUGH-66S94W Number: 20SENE

Qtrqtr: SENE Sec: 20 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.511289 Longitude: -107.904530

CORRECTIVE ACTIONS:

2 CA# 159431

Corrective Action: Install or repair required BMPs

Date: 03/31/2022

Response: CA COMPLETED

Date of Completion: 02/02/2022

Operator Comment: The access road / crossing are maintained as needed. Runoff water noted in inspection photos is coming from drainage areas above the water crossing and is laden with naturally occurring sediment that is coming from areas above the crossing. The road and crossing are constructed in alluvial deposits with a high rock content which helps to stabilize the crossing and prevents down-cutting by occasional traffic. The crossing and occasional light truck traffic are not contributing significant sources of sediment to the snow melt runoff that occasionally runs in this drainage.

COGCC Decision: _____

COGCC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective action #159431 has been addressed. If requested, TEP will meet on-site with the inspector to evaluate further.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: _____

Title: TEP ENV

Date: 2/2/2022 4:43:12 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
-------------------------------	---------------------------

--	--

Total Attach: 0 Files