

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/02/2022

Submitted Date:

01/28/2022

Document Number:

696900174**FIELD INSPECTION FORM**Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
CHESSON, BOB 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10711Name of Operator: PAINTED PEGASUS PETROLEUM LLCAddress: 16820 BARKER SPRINGS RD #521City: HOUSTON State: TX Zip: 77084**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Medina, Justin		justin.medina@state.co.us	
Axelson, John		john.axelson@state.co.us	
, TROY	713) 818-8152	tmouret@p3petro.com	All Inspections
Hickey, Mike		michael.hickey@state.co.us	
Gorka, Ray		rgorka@kpk.com	
Hix, James		james.hix@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	

General Comment:

This inspection undertaken for complaint #402934718. Complantant alleging spills/soil contamination. Complantant supplied photos shows spillage from open top netted produced water tank and surface staining from separator malfunction. Complantant contacted emergency number (713-510-0150) and no clean-up action were undertaken.

Inspection showed overflowing PW tank with fluid in bermed containment. Also separator leaking fluid at a rate of 3- to 5-gallons an hour (estimated). Call to emergency number went to voice mail and was informed that the voice mail was full. Unable to leave message regarding spill. See accompanying photos.

Mike Hickey and James Hicks of the OWP are aware of the issues. PPP is under bankruptcy process.

Environmental**Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: _____

Comment: Produced water release from PW tank (into earthen berm) and from separator (outside berm area).

Corrective Action: Release must be cleaned-up ASAP. Failure to stop and clean-up releases may result in enforcement actions. Clean-up action must be undertaken as a Form 27 and required area EPS to approve.

Date: 01/29/2022

Reportable: YES

GPS: Lat _____ Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

COGCC Comments

Comment	User	Date
This inspection undertaken for complaint #402934718. Complantant alleging spills/soil contamination. Complantant supplied photos shows spillage from open top netted produced water tank and surface staining from separator malfunction. Complantant contacted emergency number (713-510-0150) and no clean-up action were undertaken.	chessonr	01/28/2022
Inspection (1/28) showed overflowing PW tank with fluid in bermed containment. Also separator leaking fluid at a rate of 3- to 5-gallons an hour (estimated). Call to emergency number went to voice mail and was informed that the voice mail was full. Unable to leave message regarding spill. See accompanying photos.		
Mike Hickey and James Hicks of the OWP are aware of the issues. PPP is under bankruptcy process.		

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402941354	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5648556
696900175	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5648554
696900176	video clip	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5648555