

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402945194

Date Received:

02/02/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Jones, Tammy</u>		<u>tajones@hilcorp.com</u>
<u>Shorty, Priscilla</u>	<u>505-324-5188</u>	<u>pshorty@hilcorp.com</u>
<u>Killough, Mitch</u>		<u>mkillough@hilcorp.com</u>
<u>Fischer, Alex</u>		<u>alex.fischer@state.co.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 688801092
Inspection Date: 01/03/2022 FIR Submit Date: 01/04/2022 FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY Company Number: 10133
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 326514

Location Name: HUBER-LENGAL/SLAUGHTER-N34N8W Number: 10SWSW County: LA PLATA
Qtrqr: SWS Sec: 10 Twp: 34N Range: 8W Meridian: N
Latitude: 37.225190 Longitude: -107.738470

FACILITY - API Number: 05-067-00 Facility ID: 89127

Facility Name: HUBER-LENGAL/SLAUGHTER Number: 2-10
Qtrqr: SWS Sec: 10 Twp: 34N Range: 8W Meridian: N
Latitude: 37.225190 Longitude: -107.738470

CORRECTIVE ACTIONS:

1 ☒ CA# 159018

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a.

Date: 02/04/2022

Response: CA COMPLETED

Date of Completion: 01/25/2022

Operator Comment: Comment from operator: We dug down about 6" x 3'x3' and removed all the contaminated soil. We power washed the skid and fixed the exhaust pipe from leaking moisture on the ground with a clamp and exhaust tape, all impacted soil was removed. We disposed of 3.5 – 5gal buckets of contaminated soil at the office contaminated soil bin. See attached photos

COGCC Decision: Approved pending re-inspection

COGCC Representative:

2 ☒ CA# 159019

Corrective Action: Install sign to comply with Rule 605.d.

Date: 03/04/2022

Response: CA COMPLETED

Date of Completion: 02/02/2022

Operator Comment: New well sign posted. See attached photo.

COGCC Decision: Approved via an AMI

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Priscilla Shorty

Signed: _____

Title: OperationsRegulatory Tech

Date: 2/2/2022 11:45:52 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402945194	FIR RESOLUTION SUBMITTED
402945205	Huber-Lengal Slaughter 2-10_Resolved Photos

Total Attach: 2 Files