

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402882875

Date Received:
11/30/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

General

sjninspections@ikavenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693903817

Inspection Date: 10/29/2021

FIR Submit Date: 11/04/2021

FIR Status: _____

Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 326125

Location Name: TUBBS 32-6-9-N32N6W Number: 9SESW County: LA PLATA

Qtrqr: SESW Sec: 9 Twp: 32N Range: 6W Meridian: N

Latitude: 37.027501 Longitude: -107.510165

FACILITY - API Number: 05-067-00 Facility ID: 215912

Facility Name: TUBBS 32-6-9 A Number: 1

Qtrqr: SESW Sec: 9 Twp: 32N Range: 6W Meridian: N

Latitude: 37.027501 Longitude: -107.510165

CORRECTIVE ACTIONS:

1 CA# 157463

Corrective Action: -Remove and properly dispose of debris by 11/20/2021. Manage weeds to prevent debris.

Date: 11/20/2021

Response: CA COMPLETED

Date of Completion: 11/30/2021

Operator Comment: completed. see attached work completed

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 CA# 157464

Corrective Action: Treat and remove saltcedar trees by 11/20/2021.

Date: 11/20/2021

Response: CA COMPLETED

Date of Completion: 11/23/2021

Operator Comment: treated and removed salt cedar trees see attached pdf work completed

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

3 CA# 157465

Corrective Action: -Erosion controls such as crimped in mulch, hydromulch, straw blanket, etc., need to be installed and maintained in the western project area until stabilized with desirable perennial vegetation, by 11/20/2021.

Date: 11/20/2021

Response: CA COMPLETED

Date of Completion: 11/30/2021

Operator Comment: This corrective action is NOT located on SIMCOE Wellsite pad. It is a LOGOS Operating LLC called Tubbs #001MV, API number is 05-067-05780. (photo attached of sign). Please review location of photo 5 in original FIR as this is not a SIMCOE site and is not within the SIMCOE well pad area.

COGCC Decision: **Not Approved**

COGCC Representative: Operator response does not demonstrate that corrective action is addressed. Any factual review requests for inspections need to be submitted within 7 days of inspection submittal and provide documentation that supports the request, such as (for this inspection) a delineation of both project areas, agreed on by both operators, showing the project disturbance boundary for the Simcoe location and the adjacent Logos location. For additional guidance on the factual review request process please refer to:
https://cogcc.state.co.us/documents/home/announcements/Field_Inspection_Report_Resolution.pdf

OPERATOR COMMENT AND SUBMITTAL

Comment: Please review 3rd corrective action. It is not a SIMCOE location. See attached picture of operator and asset owner. other CA are completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Karin Rhodes

Signed: _____

Title: admin asst

Date: 11/30/2021 1:44:09 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402882875	FIR RESOLUTION SUBMITTED
402882903	2 CAs completed
402882910	Logos Sign for area noted in CA for erosion control
402882911	original written order - see photo 5

Total Attach: 4 Files