

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402949947

Date Received:  
02/07/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635  
Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name Phone Email  
TEP 970-285-9377 COGCCInspectionReports@terraep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 700703736  
Inspection Date: 01/13/2022 FIR Submit Date: 01/19/2022 FIR Status:

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 324214

Location Name: CLOUGH-66S94W Number: 14SWSE County:  
Qtrqr: SWSE Sec: 14 Twp: 6S Range: 94W Meridian: 6  
Latitude: 39.520949 Longitude: -107.853329

FACILITY - API Number: 05-045-00 Facility ID: 324214

Facility Name: CLOUGH-66S94W Number: 14SWSE  
Qtrqr: SWSE Sec: 14 Twp: 6S Range: 94W Meridian: 6  
Latitude: 39.520949 Longitude: -107.853329

CORRECTIVE ACTIONS:

1 CA# 159264

Corrective Action: All leasehold roads will be constructed to accommodate all weather access by local emergency vehicles, and will be maintained in a stable condition.

Date: 02/18/2022

Response: CA COMPLETED

Date of Completion: 01/26/2022

Operator Comment: At the time of this inspection, the road was snowy (right after a large snow storm), but open and accessible as evidenced by the inspection photos. Rule 603.1 states: "Access Roads. At the time of construction, all leasehold roads will be constructed to accommodate all weather access by local emergency vehicles, and will be maintained in a stable condition." However, there is no requirement for the location to be plowed as implied in the photographs. Emergency vehicles can reach this location via existing access roads. TEP requests that the inspector please site specific rules for all corrective actions.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

--

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Corrective action has been addressed / completed.

--

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: \_\_\_\_\_

Title: TEP ENV

Date: 2/7/2022 5:06:26 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

<b><u>Document Number</u></b>	<b><u>Description</u></b>

Total Attach: 0 Files