

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402949947

Date Received:
02/07/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>TEP</u>	<u>970-285-9377</u>	<u>COGCCInspectionReports@terraep.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 700703736
Inspection Date: 01/13/2022 FIR Submit Date: 01/19/2022 FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 324214

Location Name: CLOUGH-66S94W Number: 14SWSE County: _____
Qtrqtr: SWSE Sec: 14 Twp: 6S Range: 94W Meridian: 6
Latitude: 39.520949 Longitude: -107.853329

FACILITY - API Number: 05-045-00 Facility ID: 324214

Facility Name: CLOUGH-66S94W Number: 14SWSE
Qtrqtr: SWSE Sec: 14 Twp: 6S Range: 94W Meridian: 6
Latitude: 39.520949 Longitude: -107.853329

CORRECTIVE ACTIONS:

1 CA# 159264

Corrective Action: All leasehold roads will be constructed to accommodate all weather access by local emergency vehicles, and will be maintained in a stable condition. Date: 02/18/2022

Response: CA COMPLETED Date of Completion: 01/26/2022

Operator Comment: At the time of this inspection, the road was snowy (right after a large snow storm), but open and accessible as evidenced by the inspection photos. Rule 603.1 states: "Access Roads. At the time of construction, all leasehold roads will be constructed to accommodate all weather access by local emergency vehicles, and will be maintained in a stable condition." However, there is no requirement for the location to be plowed as implied in the photographs. Emergency vehicles can reach this location via existing access roads. TEP requests that the inspector please site specific rules for all corrective actions.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

--

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective action has been addressed / completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: _____

Title: TEP ENV

Date: 2/7/2022 5:06:26 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
402949947	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files