

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/10/2022

Submitted Date:

02/11/2022

Document Number:

689501329**FIELD INSPECTION FORM**

Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
Brown, Kari 2A Doc Num: _____

Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		COGCCInspections@Oxy.com	All Inspections
Gregory Hamilton		Gregory_Hamilton@oxy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
481214	SPILL OR RELEASE	CL			-	Lorenz 14-35, Big Geo O SA	EI

General Comment:

This is an environmental inspection of Remediation Project 20070/Spill ID 481214 (CL). Any corrective actions from previous inspections that have not been addressed are still applicable.

There were no operator or contract environmental personnel on location at the time of this field inspection.

Photos attached to document site conditions.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type OTHER

Comment: Orange construction fencing present around open excavations. Fencing around eastern excavation beginning to fall down.

Corrective Action: Repair fencing around open excavation.

Date: 02/24/2022

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Environmental**Spills/Releases:**

Type of Spill: _____

Estimated Spill Volume: _____

Comment: Two shallow excavations were observed on location. Excavation and site area was snow-covered; the presence or absence of impacts in the excavation area could not be observed.

Corrective Action: Submit an updated Supplemental Form 27 for the remediation of this release.

Date: 03/10/2022

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Waste Management:

Type	Management	Condition	GPS (Lat)	(Long)
Comment	No E&P Waste stored on site.			
Corrective Action				Date: _____

Spill/Remediation:

Comment: _____

Corrective Action: _____

Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689501330	Eastern Excavation Fencing	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5662900
689501331	Location Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5662901