

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-66S95W /32SENW

Location ID: 324108



Photo #5990 from entrance to location.



Photo #5991 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-66S95W /32SENW

Location ID: 324108



Photo #5992 Access road lacks stabilization.




Photo #5993 Insufficient track BMP located at entrance to location.