

Document Number:
402890815

Date Received:
12/07/2021

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 47120 Contact Name: CANDICE BARBER
 Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP Phone: (307) 233-4513
 Address: P O BOX 173779 Fax: _____
 City: DENVER State: CO Zip: 80217- Email: CANDICE_BARBER@OXY.COM

For "Intent" 24 hour notice required, Name: _____ Tel: _____
 COGCC contact: Email: _____

Type of Well Abandonment Report: Notice of Intent to Abandon Subsequent Report of Abandonment

API Number 05-123-32275-00
 Well Name: COOLEY Well Number: 12-16
 Location: QtrQtr: SWSW Section: 16 Township: 2N Range: 68W Meridian: 6
 County: WELD Federal, Indian or State Lease Number: _____
 Field Name: WATTENBERG Field Number: 90750

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.134198 Longitude: -105.013533
 GPS Data: GPS Quality Value: 2.0 Type of GPS Quality Value: PDOP Date of Measurement: 11/19/2021

Reason for Abandonment: Dry Production Sub-economic Mechanical Problems
 Other _____

Casing to be pulled: Yes No Estimated Depth: _____
 Fish in Hole: Yes No If yes, explain details below
 Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below
 Details: _____

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
CODELL	7595	7609	10/08/2020	B PLUG CEMENT TOP	7265
NIOBRARA	7318	7474	10/08/2020	B PLUG CEMENT TOP	7265

Total: 2 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status
SURF	12+1/4	8+5/8	J-55	24	0	950	600	950	0	VISU
1ST	7+7/8	4+1/2	I-80	11.6	0	8180	232	8180	6620	CBL
				Stage Tool	5443	5445	652	5444	1250	CBL

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 7265 with 2 sacks cmt on top. CIBP #2: Depth 260 with 80 sacks cmt on top.
 CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
 CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 80 sks cmt from 260 ft. to 10 ft. Plug Type: STUB PLUG Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:

Perforate and squeeze at 4374 ft. with 4 sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at 2350 ft. with 142 sacks. Leave at least 100 ft. in casing 2290 CICR Depth
 Perforate and squeeze at 1441 ft. with 150 sacks. Leave at least 100 ft. in casing 1381 CICR Depth

(Cast Iron Cement Retainer Depth)

Set 87 sacks half in. half out surface casing from 1050 ft. to 765 ft. Plug Tagged:

Set 1 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: 990 ft. of 4+1/2 inch casing Number of Days from Setting Surface Plug to Capping or Sealing the Well: 8
 Surface Plug Setting Date: 11/10/2021 Cut and Cap Date: 11/18/2021

*Wireline Contractor: PATRIOT

*Cementing Contractor: NEXTIER & BASIC

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1105 Yes No

Technical Detail/Comments:

CONTINUED PLUGGING PROCEDURE:
 PERF AT 1220' WITH 75 SACKS CEMENT, CICR SET AT 1060'

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: CANDICE BARBER

Title: REGULATORY ANALYST Date: 12/7/2021 Email: DJPOSTDRILL@ANADARKO.COM

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: Jacobson, Eric Date: 2/22/2022

CONDITIONS OF APPROVAL, IF ANY: _____

Condition of Approval

COA Type

Description

0 COA	

Attachment List

Att Doc Num

Name

402890815	FORM 6 SUBSEQUENT SUBMITTED
402890840	OPERATIONS SUMMARY
402890843	CEMENT BOND LOG
402890844	OTHER
402890847	CEMENT JOB SUMMARY
402890848	WELLBORE DIAGRAM
402890851	WIRELINE JOB SUMMARY

Total Attach: 7 Files

General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)