

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

RECEIVED

C-17366

SUNDRY NOTICES AND REPORTS ON WELLS

JAN 22 1976

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal

9. WELL NO.

2-23X

10. FIELD AND POOL, OR WILDCAT

Blue Gravel

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 23-T9N-R91W

12. COUNTY OR PARISH

Moffat

13. STATE

Colorado

1. OIL WELL GAS WELL OTHER **Dry hole**

2. NAME OF OPERATOR

C & K Petroleum, Inc.

3. ADDRESS OF OPERATOR

Suite 1700, 1600 Broadway, Denver, Colorado 80202

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1400' FNL; 2020' FWL Sec. 23



14. PERMIT NO.

Colo. 75 47

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6800' Gr.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Operations temporarily suspended. Plug screwed into top of 4 1/2" casing with 2000# valve. All pits are fenced.

Proposed abandonment:

Plug Back Total Depth 4576'. Filled with sand 4576-4500'. Proposed to place 10 sx. cement plug 4500-4290', fill with sand to 4225', place 10 sx cement plug 4225' to 4115', fill with sand 4115' to 3930', place 10 sx. cement plug 3930' to 3820'. Shoot off 4 1/2" casing and pull from approximately 3000'. Place 10 sx cement plug in top of remaining casing. ① Place 15 sx cement plug across bottom of 8 1/2" surface pipe (306'). ② Place 10 sx cement plug and regulation marker in top of surface casing. Clear and level pits and location. Reseed.

① Plus 100ft cmt plug on top csq stab.

② Cmt plug from 315' - 240'

③ Load hole w/ 9.5 #/gal mud

DVRT	
FJP	
HFM	✓
JAM	✓
JJO	
GCH	
CGM	

18. I hereby certify that the foregoing is true and correct

SIGNED

George E. Farmer

TITLE

Division Operations Manager DATE July 22, 1975

(This space for Federal or State office use)

APPROVED BY

[Signature]

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

[Handwritten mark]