

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/25/2022

Submitted Date:

02/28/2022

Document Number:

690202626**FIELD INSPECTION FORM**Loc ID 308487 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10705Name of Operator: EVERGREEN NATURAL RESOURCES LLCAddress: 1875 LAWRENCE ST STE 1150City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, Evergreen		cogcc.evergreen@enrllc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272827	WELL	PR	09/22/2004	GW	071-08113	CHATEAU 34-14	RI
278519	PIT	AC	06/24/2005		-	CHATEAU 34-14 ONSITE	AC

**General Comment:**

This is a follow up of the previous inspections; #690201985, #690202163.  
Corrective actions of the previous inspections have not been performed.  
See attached photos and additional details within this report.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type

OTHER

Comment:

There are exposed flowlines along the road. The lines should be buried with sufficient cover to protect the line from potential damage. This area of erosion should have been repaired with the previous stormwater corrective action date of 9/30/2021.

Corrective Action:

Cover flowline sufficient to protect from damage to comply with rule 1102.e.

Date: 09/30/2021

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Fail			

Comment: There are culverts along the main road that are partially washed out and filled in with debris. There is erosion along the side of the road which has exposed a flowline. There is erosion along the access road with insufficient BMP's causing stormwater to flow down a long stretch of the road side. Areas of erosion need to be repaired and stabilized. Previous corrective action was not performed.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 09/30/2021

**Pits:** ☐ NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 278519 Lat: 37.079175 Long: -104.637972

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: \_\_\_\_\_ Fencing Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_ Oil Accumulation: NO 2+ feet Freeboard: \_\_\_\_\_

Comment: The pit is not constructed to allow 2 ft. of freeboard due to shallow depth of pit.

Corrective Action Comply with Rule 909.

Date: 11/13/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
402968120	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5676230">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5676230</a>
690202628	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5676226">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5676226</a>