

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402608620

Date Received:

02/24/2021

Spill report taken by:

NEIDEL, KRIS

Spill/Release Point ID:

447425

SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 906.b. for reporting requirements of spills or releases of E&P Waste or produced fluids. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

OPERATOR INFORMATION

Name of Operator: CHEVRON USA INC	Operator No: 16700	Phone Numbers Phone: (970) 675-3814 Mobile: (307) 871-5363 Email: spwu@chevron.com
Address: 760 HORIZON DRIVE STE 401		
City: GRAND JUNCTION	State: CO Zip: 81506	
Contact Person: Chris Patterson		

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 401098202

Initial Report Date: 08/24/2016 Date of Discovery: 08/22/2016 Spill Type: Recent Spill

Spill/Release Point Location:

QTRQTR NENW SEC 34 TWP 2N RNG 102W MERIDIAN 6

Latitude: 40.104392 Longitude: -108.828672

Municipality (if within municipal boundaries): County: RIO BLANCO

Reference Location:

Facility Type: ☐ Facility/Location ID No ☒ Well API No. (Only if the reference facility is well) 05-103-09149
Spill/Release Point Name: ☐ No Existing Facility or Location ID No.

Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? No
Secondary containment, **including walls & floor regardless of construction material**, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

Were Five (5) barrels or more spilled? Yes

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): >0 and <1 Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0 Estimated Produced Water Spill Volume(bbl): 0

Estimated Other E&P Waste Spill Volume(bbl): 0 Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: 60BBLS of fresh water were released with 0.01BBLS of oil

Land Use:

Current Land Use: NON-CROP LAND Other(Specify):

Weather Condition: Sunny and warm

Surface Owner: FEDERAL Other(Specify): BLM

Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State ☐ Residence/Occupied Structure ☐ Livestock ☐ Public Byway ☐ Surface Water Supply Area ☐

As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

Monday (8/22) at approximately 11:20 am a release occurred from a drained 2" fiberglass line that was being washed with fresh water prior to being capped to be put out of service at Carney 41Y34 (API 05-103-06149) Approximately 60 bbls of potable rinse water and 0.01 bbls of oil were released. Approximately 30 BBLS of water was recovered, and all the oil was recovered. The flush was stopped immediately upon detection. The oil affected area has been water washed. The line will remain out of service until repaired.

List Agencies and Other Parties Notified:

Was there a Grade 1 Gas Leak? Yes ☐ No ☐

If YES, enter the Document Number of the Grade 1 Gas Leak Report Form 44: _____

Was there a reportable accident associated with either a Grade 1 Gas Leak or an E&P waste spill or release? Yes ☐ No ☐

If YES, enter the Document Number of the Initial Accident Report, Form 22: _____

Was there damage during excavation? Yes ☐ No ☐

If YES, was CO 811 notified prior to excavation? Yes ☐ No ☐

CORRECTIVE ACTIONS

#1 Supplemental Report Date: 02/24/2021

Root Cause of Spill/Release Pipe, Weld, or Joint Failure

Other (specify) _____

Type of Equipment at Point of Spill/Release: Process Piping

If "Other" selected above, specify or describe here:

Describe Incident & Root Cause (include specific equipment and point of failure)

Monday (8/22) at approximately 11:20 am a release occurred from a drained 2" fiberglass line that was being washed with fresh water prior to being capped to be put out of service at Carney 41Y34 (API 05-103-06149) Approximately 60 bbls of potable rinse water and 0.01 bbls of oil were released. Approximately 30 BBLS of water was recovered, and all the oil was recovered. The flush was stopped immediately upon detection. The oil affected area has been water washed. The line will remain out of service until repaired. Line ruptured during flushing.

Describe measures taken to prevent the problem(s) from reoccurring:

Placed line out of service.

Volume of Soil Excavated (cubic yards): _____

Disposition of Excavated Soil (attach documentation) ☐ Offsite Disposal ☐ Onsite Treatment
☐ Other (specify) _____

Volume of Impacted Ground Water Removed (bbls): _____

Volume of Impacted Surface Water Removed (bbls): _____

REQUEST FOR CLOSURE

Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.

Basis for Closure: ☒ Corrective Actions Completed (documentation attached)

☐ Work proceeding under an approved Form 27

Form 27 Remediation Project No: _____

OPERATOR COMMENTS:

The area noted on the Form 19 was walked and soil was probed with a shovel to identify any notable impacts and assure that

representative samples were collected on 4/1/2020. No hydrocarbon odors or salt staining were observed. All samples are within the COGCC Table 910-1 allowable concentrations. Chevron is requesting closure of Spill ID 401098202 under Table 910-1 due to the initial release occurring during Table 910-1 rule. Samples were collected prior to the Table 915 adoption.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: _____ Print Name: Chris Patterson

Title: Lead HSE Specialist Date: 02/24/2021 Email: spwu@chevron.com

Condition of Approval

COA Type

Description

	Based on review of information presented it appears that no further action is necessary at this time, and COGCC approves the closure request. However, should future conditions at the site indicate contaminant concentrations in soils exceeding COGCC standards or if groundwater is found to be impacted, then further investigation and/or remediation activities may be required at the site.
--	---

1 COA

Attachment List

Att Doc Num

Name

402608620	SPILL/RELEASE REPORT(SUPPLEMENTAL)
402608637	ANALYTICAL RESULTS
402982590	FORM 19 SUBMITTED

Total Attach: 3 Files

General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)