

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/18/2022

Submitted Date:

03/22/2022

Document Number:

690900197

**FIELD INSPECTION FORM**Loc ID 324591 Inspector Name: FISCHER, ALEX On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

4 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	ALL INSPECTIONS
Neidel, Kris		kris.neidel@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
465486	NEW	AC	11/19/2020		-	Dwinell Tank Battery	EI

**General Comment:**

On March 18, 2022, COGCC Environmental Staff (Alex Fischer) conducted a field inspection of KP Kauffman Company Inc's (KPK) Dwinell (Location ID: 324591). The inspection was a follow up to Spill ID 473059 and REM 15326. Weather was sunny, temperature about 5 degrees Fahrenheit, and snow cover on the ground. For the most recent environmental field inspection report of this facility, please refer to Document #690900195.

The following is a summary:

County Road 8B was inaccessible from the cattle guard approximately 430' from County Road 8 to the Dwinell facility due to drifted snow. Operator in violation of Rules 204 and 603.I.

Any corrective action(s) and corrective action due dates from previous inspections that have not been addressed are still applicable.

**Location**

<b>Lease Road:</b>			
Type	Main		
comment:	County Road 8B was inaccessible from the cattle guard approximately 430' from County Road 8 to the Dwinell facility due to drifted snow.		
Corrective Action:	Repair and maintain lease road to comply with rule 204 and 603.I.	Date:	04/22/2022

Overall Good: ☐

Emergency Contact Number:

Comment:			
Corrective Action:			
		Date:	

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 465486    Type: NEW    API Number: -    Status: AC    Insp. Status: EI

**COGCC Comments**

Comment	User	Date
<p>On March 18, 2022, COGCC Environmental Staff (Alex Fischer) conducted a field inspection of KP Kauffman Company Inc's (KPK) Dwinell (Location ID: 324591). The inspection was a follow up to Spill ID 473059 and REM 15326. Weather was sunny, temperature about 5 degrees Fahrenheit, and snow cover on the ground. For the most recent environmental field inspection report of this facility, please refer to Document #690900195.</p> <p>The following is a summary:  County Road 8B was inaccessible from the cattle guard approximately 430' from County Road 8 to the Dwinell facility due to drifted snow.  Operator in violation of Rules 204 and 603.I.  Any corrective action(s) and corrective action due dates from previous inspections that have not been addressed are still applicable.</p>	fischera	03/22/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690900198	KPK Dwinell TB Loc 324591, Spill 473059 REM 15326 20220318 Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5700599">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5700599</a>