



Flood created spill Bondad 33-9#22A

Darren Rowley <drowley@logosresourcesllc.com>

Fri, Jul 30, 2021 at 6:46 PM

To: "jimo.hughes@state.co.us" <jimo.hughes@state.co.us>

Cc: Marie Florez <mflorez@logosresourcesllc.com>, Marcia Brueggjenjohann <mbrueggjenjohann@logosresourcesllc.com>, Robert Bixler <rbixler@logosresourcesllc.com>

Mr. Hughes,

As per our conversations over the last few days regarding the Bondad 33-9#22A. Logos operating believes less than 1 barrel of compressor oil and produced was released into containment and less than 5 gallons ended up outside of that containment (this is only a best estimate). We were unable to locate any signs of this flood created release greater than a few feet from the containment ring. It appears that the containment did its job. Above are pictures of how we found the BGT yesterday after Tuesday evening's act of God flooding, and how it looked at the end of today following our initial cleanup.

Logos Operating will remove and properly manage gravel, rock, and material displaced and discharged downslope of the well pad as soon as a one call can be cleared and crews become available. Logos operating began working on this issue as soon as it came to our attention and will continue to resolve the issues until they are complete. We will be filing the rest of the required paperwork on Monday 8/2/2021.

Please let me know if you have any questions or concerns.

Thank you,

Darren Rowley

Operations Area 4

505-947-4974



7 attachments

After initial clean up 1.jpg
148K



After initial clean up 2.jpg
152K



After initial clean up 3.jpg
141K




Before cleanup #1.jpg
152K



Before cleanup #2.jpg
161K

Before cleanup #3.jpg
150K



 **insp_402766562.pdf**
91K