

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/14/2022

Submitted Date:

04/18/2022

Document Number:

700600378**FIELD INSPECTION FORM**Loc ID 461219 Inspector Name: Kosola, Jason On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 61650Name of Operator: MURFIN DRILLING COMPANY INCAddress: 250 N WATER ST STE 300City: WICHITA State: KS Zip: 67202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Rodak, Leon	316-858-8616	lrodak@murfininc.com	Principal Agent
Melland, Tom	316-858-8695	tmelland@murfininc.com	Production Engineer
Esquivel, James	620-272-4913	j280189@pld.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

General Comment:

Improper abandonment of flowline or crude oil transfer line (not purged, depressurized, risers cut 3' below grade, ends sealed, equipment removed) per 1105. Disconnected flowline risers not OOSLAT (out of service locks and tags).

Please note 24 hour corrective action.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	OTHER		
Comment:	Improper abandonment of flowline or crude oil transfer line (not purged, depressurized, risers cut 3' below grade, ends sealed, equipment removed) per 1105. Disconnected flowline risers not OOSLAT (out of service locks and tags).		
Corrective Action:	Complete flowline and crude oil transfer line abandonments to comply with Rule 1105. 24 hrs to OOSLAT; 30 Days to complete abandonments per 1105		Date: 04/19/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
Crude Oil	Truck Loadout			
Comment:	Stained soil inside containment and around truck loadout			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.			Date: 05/19/2022

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
700600379	Inspection photos	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5726453