

Inspection Photos

4/22/2022

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335306

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 335306



Photo 1: Photo example of the adjacent reference areas.



Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335306



Photo 2: Photos 2-3 taken from the south end of the Location facing west, northwest, northeast to east. Photos provide overview of the Location. Photos also show areas of the Location not progressing towards 1003 standards. .

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335306



Photo 3: See comments under photo 2.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335306



Photo 4: Photos taken from the northeast end of the Location, facing northwest and northeast. Photos show areas on the north and east end of the Location are not progressing towards 1003 standards.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 335306



Photo 5: Photos taken from the west end of the Location. Photos show western interim areas where vegetation IS progressing towards 1003 standards.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 335306



Photo 6: Photos taken from the slopes on the east end of the Location. Photos show control measures to minimize erosion and degradation on the eastern slopes of the Location are missing or inadequate; Two rows of erosion logs observed on slopes; BMPs have not been installed per good engineering or maintained in proper functioning condition; No additional controls observed in conjunction with erosion logs to minimize erosion/degradation on slopes; erosion degradation evident on slopes, and has cut beneath wattles.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 335306



Photo 7: Photo shows fence panels at wells in disrepair.

