

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

04/26/2022

Submitted Date:

04/27/2022

Document Number:

693904443**FIELD INSPECTION FORM**
 Loc ID 306896 Inspector Name: ROY, CATHERINE On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10749Name of Operator: SIMCOE LLCAddress: 1199 MAIN AVE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
, General		sjninspections@ikavenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274639	WELL	PR	12/01/2021	GW	067-08991	GOEGLEIN 2	RI

General Comment:

On 4/26/2022 Catherine Roy conducted a reclamation and stormwater inspection. During this inspection the following compliance issues were observed:

-Assess and maintain stormwater controls. Additional BMPs need to be installed where existing controls are not adequate. Corrective action date: 5/27/2022

See below, and attached photos for additional detail.

Inspected Facilities				
Facility ID: 274639	Type: WELL	API Number: 067-08991	Status: PR	Insp. Status: RI

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Stormwater controls are installed in response to 2020 reclamation inspection. However, BMPs are full of sediment and needing maintenance. Additional BMPs appear needed at discharge points within the project area.

Corrective Action: -Assess and maintain stormwater controls. Additional BMPs need to be installed where existing controls are not adequate. Corrective action date: 5/27/2022

Date: 05/27/2022

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693904444	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5736947