

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

04/25/2022

Submitted Date:

04/25/2022

Document Number:

699105283**FIELD INSPECTION FORM**
 Loc ID 422923 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 8960Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANYAddress: 410 17TH STREET SUITE #1400City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
422937	WELL	SI	12/01/2020	OW	123-33453	FRENCH LAKE 3-62-6 1H	TA

**General Comment:**

**Location**Overall Good: ☒**Signs/Marker:**

Type	OTHER		
Comment:	Entrance		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Adequate	Date:	
Corrective Action:			

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused Equipment next to the well needs to be removed for good housekeeping. See attached photos.		
Corrective Action:	Comply with Rule 606. Submit pictures with FIRR	Date:	06/03/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	Barbwire		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Panel		
Corrective Action:		Date:	

**Equipment:**

Type: Bradenhead	# 1		corrective date
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Other	#		
Comment:	Unmarked/Unused risers needs marked. See attached photos		
Corrective Action:	Upon removing a flowline or crude oil transfer line from use with the intent to abandon, an operator must immediately apply OOSLAT to the risers. OOSLAT must stay in place at all times during the process of abandoning the flowline or crude oil transfer line until the operator removes the riser. Comply with Rule 1105.b. Submit pictures with FIRR		Date: 06/03/2022
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 422937 Type: WELL API Number: 123-33453 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: T/A  
Last MIT recored was on 11-2-2020

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**Date of Last Brhd Test: 06/22/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Monday 4/25/22 at approximately 1027hrs, I, Inspector Adam Burns, Conducted an on-site inspection at French Lake 3-62-6 1H of Civitas, at API # 05-123-33453 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Unused Equipment next to the well needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 6/3/22</p> <p>Unmarked/Unused risers needs marked. Upon removing a flowline or crude oil transfer line from use with the intent to abandon, an operator must immediately apply OOSLAT to the risers. OOSLAT must stay in place at all times during the process of abandoning the flowline or crude oil transfer line until the operator removes the riser. Comply with Rule 1105.b. With a corrective action date of 6/3/22</p> <p>See attached photos.</p> <p>Submit pictures on FIRR.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	burnsa	04/25/2022

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403026344	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5734157">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5734157</a>
699105284	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5734147">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5734147</a>