

**FORM  
INSP**Rev  
X/20

# State of Colorado Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

04/22/2022

Submitted Date:

04/26/2022

Document Number:

702700118**FIELD INSPECTION FORM**
 Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
 \_\_\_\_\_ Anderson, Laurel \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**10 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
LLC, MarCom	208-201-8280	PrimaryContractor@marcomllc.net	<a href="#">KPK Primary Contractor</a>
Gorka, Ray		RGorka@kpk.com	<a href="#">KPK environmental</a>
, KPK		cogcc@kpk.com	<a href="#">All Inspections</a>
Rickard, Jeff		JRickard@kpk.com	<a href="#">KPK environmental</a>
Brown, Kari		kari.oakman@state.co.us	
Graber, Nikki		nikki.graber@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
478086	SPILL OR RELEASE	CL	01/15/2021		-	UPRR 43 PAN AM G Consolidation #2	EI

**General Comment:**

This is an environmental inspection of Remediation No. 16131/Spill ID 478086 (CL). Any corrective actions from previous inspections that have not been addressed are still applicable.

[Photos attached to document site conditions.](#)

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds/debris throughout site and within open excavation (See Photos).		
Corrective Action:	Comply with Rule 606.		Date: 05/03/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Fencing around open excavation does not adequately protect access to the site.		
Corrective Action:	Secure access to excavation in compliance with Rule 913.b.(5).B.i and COGCC Guidance 913.b.(5)B i-v.		Date: 04/28/2022

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:



**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_

Estimated Spill Volume: \_\_\_\_\_

Comment: Spill excavation is open. Impacts remain in-situ. Hydrocarbon sheen observed on groundwater in open excavation. Form 27 Doc #402896678 states excavation work is ongoing; However, no work was being conducted during this environmental inspection.

Corrective Action: Submit a Supplemental Form 27 with an updated implementation schedule.

Date: 05/22/2022

Reportable: \_\_\_\_\_

GPS: Lat \_\_\_\_\_

Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat

Long

DWR Receipt Num: \_\_\_\_\_

Owner Name: \_\_\_\_\_

GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Comment: \_\_\_\_\_

**Spill/Remediation:**

Comment: Oily waste is stored onsite without any BMPs to contain runoff. Unconsolidated earthen berm around stockpiled soils has failed. No liner beneath stockpile was observed. No waste signage has been installed. Sensitive receptors (county road, residence, Big Dry Creek) are present on all sides of the spill location.

Corrective Action: Manage waste in compliance with Rule 913.b.iv and COGCC Guidance 913.b.(5)B i-v.

Date: 06/29/2021

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_

Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No BMPs in place to control stormwater runoff.](#)Corrective Action: [Install BMPs in accordance with 1002.f.\(2\).](#)

Date: 05/11/2022

**Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403028432	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5735968">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5735968</a>
702700120	Site Inspection Documentation	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5735964">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5735964</a>