

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403035776

Date Received:

05/03/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

4 of 5 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Mike Storey

Phone

970-939-6353

Email

mstorey@civiresources.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 699105307

Inspection Date: 04/28/2022

FIR Submit Date: 04/29/2022

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Company Number: 8960

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 450201

Location Name: Longhorn Number: U-10 Pad County: \_\_\_\_\_

Qtrqr: NENE Sec: 10 Twp: 3N Range: 63W Meridian: 6

Latitude: 40.246500 Longitude: -104.416044

FACILITY - API Number: 05-123-00 Facility ID: 450201

Facility Name: Longhorn Number: U-10 Pad

Qtrqr: NENE Sec: 10 Twp: 3N Range: 63W Meridian: 6

Latitude: 40.246500 Longitude: -104.416044

CORRECTIVE ACTIONS:

2 CA# 161397

Corrective Action: Comply with Rule 606.  
Submit photo with FIRR

Date: 05/06/2022

Response: CA COMPLETED

Date of Completion: 05/02/2022

Operator Comment: Trash has been removed in compliance with Rule 606.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

3 CA# 161398

Corrective Action: Comply with Rule 606.  
Submit photo with FIRR

Date: 05/06/2022

Response: CA COMPLETED

Date of Completion: 05/02/2022

Operator  
Comment: Unused equipment has been removed in compliance with Rule 606.

COGCC Decision:

COGCC  
Representative:

4 CA# 161399

Corrective Action: Upon removing a flowline or crude oil transfer line from use with the intent to abandon, an operator must immediately apply OOSLAT to the risers. OOSLAT must stay in place at all times during the process of abandoning the flowline or crude oil transfer line until the operator removes the riser. Comply with Rule 1105.b.

Date: 05/06/2022

Response: CA COMPLETED

Date of Completion: 05/02/2022

Operator  
Comment: Risers marked with OOSLAT per Rule 1105.b

COGCC Decision:

COGCC  
Representative:

5 CA# 161400

Corrective Action: "Properly dispose of oily waste in accordance with 905.e."  
Submit photos with FIRR

Date: 05/06/2022

Response: CA COMPLETED

Date of Completion: 05/02/2022

Operator  
Comment: Oily waste has been removed in accordance with 905.e

COGCC Decision:

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Aubrey Noonan

Signed: \_\_\_\_\_

Title: Regulatory Analyst

Date: 5/3/2022 8:15:05 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403035792	Inspection Photos

Total Attach: 1 Files