

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402767305

Date Received:
08/02/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1700 LINCOLN ST STE 3950

City: DENVER State: CO Zip: 80203

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Christina Pierce</u>	<u>970-263-3626</u>	<u>cpierce@Laramie-Energy.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 692402974

Inspection Date: 01/29/2021

FIR Submit Date: 02/02/2021

FIR Status: _____

Inspected Operator Information:

Company Name: LARAMIE ENERGY II LLC

Company Number: 10232

Address: 1401 SEVENTEENTH STREET #1401

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 335524

Location Name: RMV-66S93W Number: 20NWNE County: GARFIELD

Qtrqtr: NWNE Sec: 20 Twp: 6S Range: 93W Meridian: 6

Latitude: 39.517682 Longitude: -107.796096

FACILITY - API Number: 05-045-00 Facility ID: 296954

Facility Name: RMV Number: 20-01D

Qtrqtr: NWNE Sec: 20 Twp: 6S Range: 93W Meridian: 6

Latitude: 39.517682 Longitude: -107.796096

CORRECTIVE ACTIONS:

1 CA# 146293

Corrective Action: Assess vegetation in Spring 2021; reseeding / interseeding/ applying remedies as indicated to establish uniform desirable vegetation across all disturbance areas to 80% of reference area requirement.

Date: 04/01/2021

Response: CA COMPLETED

Date of Completion: 06/27/2021

Operator Comment: per inspection 692403593 issue resolved see attached inspection

COGCC Decision: Approved

COGCC Representative: Location was built. Wells were not drilled. Inspection 692403593 dated 6/27/2021 noted: "Final Reclamation had been installed. Overall Final Reclamation Status was In Process. Property, under new ownership, has had a Change of Land Use. Location is now storage yard and Building site."

No Rule 502.b reclamation variance request was submitted by the Operator. Previous Inspector passed Overall Final Reclamation on the Location, therefore this FIRR is being approved.

2 CA# 146294

Corrective Action: Install or repair sufficient/effective BMPs in accordance with, and monitoring per Good Engineering Practices per Rule 1002.f

Date: 04/01/2021

Response: CA COMPLETED

Date of Completion: 06/27/2021

Operator Comment: per inspection 692403593 issue resolved see attached inspection

COGCC Decision: Approved

COGCC Representative: Location was built. Wells were not drilled. Inspection 692403593 dated 6/27/2021 noted: "Final Reclamation had been installed. Overall Final Reclamation Status was In Process. Property, under new ownership, has had a Change of Land Use. Location is now storage yard and Building site."

No Rule 502.b reclamation variance request was submitted by the Operator. Previous Inspector passed Overall Final Reclamation on the Location, therefore this FIRR is being approved.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Christina Pierce

Signed: _____

Title: Engineering Tech

Date: 8/2/2021 11:34:07 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402767305	FIR RESOLUTION SUBMITTED
402767322	corrective action

Total Attach: 2 Files