

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402770376

Date Received:  
08/05/2021

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10728

Name of Operator: GULF EXPLORATION LLC

Address: 9701 N BROADWAY EXTENSION

City: OKLAHOMA CITY State: OK Zip: 73114

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

[scott.schultz@coag.gov](mailto:scott.schultz@coag.gov)

[parks.barroso@coag.gov](mailto:parks.barroso@coag.gov)

[sstrickland@gulfexploration.com](mailto:sstrickland@gulfexploration.com)

### COGCC INSPECTION SUMMARY:

FIR Document Number: 692402693

Inspection Date: 11/19/2020

FIR Submit Date: 12/02/2020

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: GULF EXPLORATION LLC

Company Number: 10728

Address: 9701 N BROADWAY EXTENSION

City: OKLAHOMA CITY State: OK Zip: 73114

### LOCATION - Location ID: 466705

Location Name: Eagle Hill Number: 1-32 Pad County: \_\_\_\_\_

Qtrqtr: NWNE Sec: 32 Twp: 10N Range: 78W Meridian: 6

Latitude: 40.799820 Longitude: -106.170270

### FACILITY - API Number: 05-057-00 Facility ID: 466705

Facility Name: Eagle Hill Number: 1-32 Pad

Qtrqtr: NWNE Sec: 32 Twp: 10N Range: 78W Meridian: 6

Latitude: 40.799820 Longitude: -106.170270

### CORRECTIVE ACTIONS:

1 ☒ CA# 144801

Corrective Action: Perform Final Reclamation per COGCC 1004 Rules. Due to enforcement actions CA Date is not given.

Date: \_\_\_\_\_

Response: CA COMPLETED

Date of Completion: 07/02/2021

Operator Comment: Gulf immediately sought bids from qualified contractors to regain and maintain compliance once the ground thawed. Western States was contracted to develop and implement a plan, which was communicated and accepted by COGCC staff. Temporary erosion control BMP's to control soil migration have been installed,

inspected, and maintained since December of 2020 until appropriate conditions exist to reapply seed and appropriate mulch during the fall of 2021. The pictures in the attached Corrective Actions Report document the most recent installation of Compost Filled Erosion Control Logs on the Swale on the access road to the Eagle Hill 1-32 Pad. Straw wattles installed previously were destroyed and eaten by livestock, necessitating an improvement. These BMP's were installed on July 2nd, 2021 and will continue to be inspected and maintained on a regular interval in the following months until final stabilization BMP's (seed and mulch) and winter exclusion occurs this fall. The temporary BMP's will remain in place, inspected, and maintained, until revegetation achieves 70% cover for final stabilization requirements.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules. Note: Operator Comment refers to "70% cover for final stabilization requirements." 1004 Rules require "...total percent plant cover of at least eighty percent (80%)..."

2 ☒ CA# 144802

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 08/19/2019

Response: CA COMPLETED

Date of Completion: 07/02/2021

Operator Comment: Gulf immediately sought bids from qualified contractors to regain and maintain compliance once the ground thawed. Western States was contracted to develop and implement a plan, which was communicated and accepted by COGCC staff. Temporary erosion control BMP's to control soil migration have been installed, inspected, and maintained since December of 2020 until appropriate conditions exist to reapply seed and appropriate mulch during the fall of 2021. The pictures in the attached Corrective Actions Report document the most recent installation of Compost Filled Erosion Control Logs on the Swale on the access road to the Eagle Hill 1-32 Pad. Straw wattles installed previously were destroyed and eaten by livestock, necessitating an improvement. These BMP's were installed on July 2nd, 2021 and will continue to be inspected and maintained on a regular interval in the following months until final stabilization BMP's (seed and mulch) and winter exclusion occurs this fall. The temporary BMP's will remain in place, inspected, and maintained, until revegetation achieves 70% cover for final stabilization requirements.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules. Note: Operator Comment refers to "70% cover for final stabilization requirements." 1004 Rules require "...total percent plant cover of at least eighty percent (80%)..."

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Attached is a Corrective Action Report prepared by EcoPoint, Inc.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sean Strickland

Signed: \_\_\_\_\_

Title: Operations Manager

Date: 8/5/2021 10:56:18 AM

### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
-------------------------------	---------------------------

402770376	FIR RESOLUTION SUBMITTED
402771388	Corrective Actions Report

Total Attach: 2 Files