

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403042386

Date Received:

05/09/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10758

Name of Operator: OGRIS OPERATING LLC

Address: PO BOX 53467

City: MIDLAND State: TX Zip: 79710

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
GIENA WARD	719-220-4041	gward@ogrisop.com
Thomsen, Dylan		timothy.thomsen@state.co.us
ATWATER, BONNIE	432-755-0212	batwater@ogrisop.com
O'SHIELDS, CHARLIE	940-682-5030	coshields@ogrisop.com
BACA, DAVID	719-859-4066	dbaca@ogrisop.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 690202042

Inspection Date: 09/03/2021

FIR Submit Date: 09/07/2021

FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC

Company Number: 10672

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD State: CO Zip: 8111-4978
VILLAGE

LOCATION - Location ID: 308128

Location Name: APACHE CANYON-634S68W Number: 10SESE County: LAS ANIMAS

Qtrqr: SESE Sec: 10 Twp: 34S Range: 68W Meridian: 6

Latitude: 37.093230 Longitude: -104.978280

FACILITY - API Number: 05-071- -00 Facility ID: 262543

Facility Name: APACHE CANYON Number: 10-16V

Qtrqr: SESE Sec: 10 Twp: 34S Range: 68W Meridian: 6

Latitude: 37.093230 Longitude: -104.978280

CORRECTIVE ACTIONS:

1 CA# 155545

Corrective Action: Comply with Rule 606. Remove debris.

Date: 09/17/2021

Response: CA COMPLETED

Date of Completion: 12/20/2021

Operator
Comment:

THE IMPACTED SOIL NEAR THE LIQUID RING COMPRESSOR WAS CLEANED UP AND REMOVED FROM LOCATION. THE INSULATION DEBRIS HAS BEEN PICKED UP AND REMOVED FROM LOCATION AS WELL. THE SELF INSPECTION PROCESS HAS BEEN REVIEWED.

COGCC Decision: _____

COGCC
Representative:

2 CA# 155615

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 10/01/2020

Response: CA COMPLETED

Date of Completion: 05/04/2022

Operator
Comment:

THE MAIN LEASE ROAD WAS SURFACE CROWNED TO REMOVE THE TIRE RUTS AND ESTABLISH SHEET FLOW. THE WELL PAD WAS REGRADED TO REMOVE THE TIRE RUTS.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: ALL CORRECTIVE ACTIONS HAVE BEEN ADDRESSED. SEE ATTACHED PHOTO LOG FOR DETAILS.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: GIENA WARD

Signed: _____

Title: SR. ENVIRONMENTAL TECH.

Date: 5/9/2022 1:48:49 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403042443	PHOTO LOG
-----------	-----------

Total Attach: 1 Files