

NEW ELK 36-05 API# 05-071-09236 – OGRIS OPERATING  
OGCC OPERATOR NUMBER 10758 - DATE: MAY 11, 2022  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT #690202812



PHOTO 1: THE IMPACTED SOIL NEAR THE LIQUID RING COMPRESSOR WAS CLEANED UP AND REMOVED FROM LOCATION. FRESH GRAVEL HAS BEEN REPLACED AROUND THE SKID.

NEW ELK 36-05 API# 05-071-09236 – OGRIS OPERATING  
OGCC OPERATOR NUMBER 10758 - DATE: MAY 11, 2022  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT #690202812



PHOTO 2: THE IMPACTED SOIL NEAR THE WELL WAS ALSO CLEANED UP AND REMOVED FROM LOCATION. THE SELF INSPECTION PROCESS HAS BEEN REVIEWED.