

Colorado Oil and Gas Conservation Commission

Longhorn U-10 Pad Issue Report




Created on May 13, 2022

Captured on May 13, 2022



Type	Count
Missing Part	1

No.	Type	Severity	Created	Status	Cost of Repair
1	 Missing Part	—	May 14, 2022	Open	—
					Total: \$0.00

1 - Missing Part

Open

May 13, 2022 at 7:59am



Details

Summary:	Missing/ Damaged Bird Protector
Created:	May 13, 2022, 7:42pm by Adam Burns
Cost of Repair:	—
Coordinates:	40.24621, -104.41669