

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/06/2022

Submitted Date:

05/09/2022

Document Number:

690202875

FIELD INSPECTION FORMLoc ID _____ Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10626

Name of Operator: DOVER ATWOOD CORPORATION

Address: 1875 HARSH AVENUE SE

City: MASSILLON State: OH Zip: 44646

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

8 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
LEVENGOOD JOHN		jlevengood07@gmail.com	
Kosola, Jason		jason.kosola@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
COGCC Enforcement		dnr_cogccenforcement@state.co.us	
LEVENGOOD SARAH		doveratwoodcorp@yahoo.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
438617	GAS COMPRESSOR STATION	AC	02/23/2022		-	S. Bear Creek Compressor & Treater	RI

General Comment:

This is a follow up of the previous inspection document #690202540.
Operator was verbally notified of issues during previous inspection.
The previous inspection corrective actions have not been completed.
Non-compliance of the Rules will be referred to enforcement.
See attached photos and additional details within this report.

LocationOverall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:	Sign or label not posted or information inaccurate at facility and on tanks or containers. Previous corrective action not completed.		
Corrective Action:	Install sign to comply with Rule 605	Date:	03/02/2022

Emergency Contact Number:

Comment:	The emergency contact number was not valid. Previous corrective action not completed.		
Corrective Action:	Install sign to comply with Rule 605	Date:	03/02/2022

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	There are various unused supplies pipe, fittings, containers, trash stored on location. Previous corrective action not completed.		
Corrective Action:	Comply with Rule 606	Date:	02/16/2022
Type	UNUSED EQUIPMENT		
Comment:	There is an unused compressor stored on location. Previous corrective action not completed.		
Corrective Action:	Comply with Rule 606	Date:	03/02/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
	Tank			
Comment:	There are signs that the open top tanks have leaked due to white stained soils observed. Previous corrective action not completed.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.			Date: 03/02/2022

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	100 BBLS	FIBERGLASS AST		,	
Comment:	The tank at the east side of the location is filled nearly to the top with liquids and needs to be lowered to prevent from spilling over. Operator was notified by phone call of this issue. Previous corrective action not completed.					
Corrective Action:	Comply with 912.d. Spill and Release Prevention. Comply with 902. Pollution Prevention.				Date:	02/02/2022

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
	2	100 BBLs	FIBERGLASS AST		,
Comment:	Netting on open top tanks inadequate. Previous corrective action not completed.				
Corrective Action:	Install or repair wildlife protection equipment. Comply with 902.b.				Date: 02/07/2022

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
	Inadequate				
Comment:	There is no secondary containment installed at the open top tanks. Previous corrective action not completed.				
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 912.d.(1).				Date: 03/02/2022

Venting:

Yes/No				
Comment:				
Corrective Action:	Date:			

Flaring:

Type				
Comment:				
Corrective Action:	Date:			

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403041624	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5747723
690202876	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5747718