

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type OTHER

Comment: PHOTO 4: AREA OF IMPACTED SOIL NEAR PRIME MOVER ENGINE SKID.

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002.(2).D.

Date: 05/30/2022

Overall Good:

Spills:

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type WELLHEAD

Comment:

Corrective Action:

Date:

Type LOCATION

Comment:

Corrective Action:

Date:

Equipment:

corrective date

Type: Bradenhead # 1

Comment: IS ACCESSABLE

Corrective Action:

Date:

Type: Ancillary equipment # 1

Comment:

Corrective Action:

Date:

Type: Gas Meter Run # 1

Comment: CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.

Corrective Action:

Date:

Type: Vertical Separator # 1

Comment:

Corrective Action:

Date:

Type: Deadman # & Marked # 4

Comment:

Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:			
Corrective Action:		Date:	
Type: Progressive Cavity	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 217297 Type: WELL API Number: 071-06073 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 04/22/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 7 Fluid Type: NONE

End Surf Csg Pressure: 58

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Culverts	Pass			
		Gravel	Pass			

Comment: PHOTO 5: OILY WASTE IN PRIME MOVER ENGINE SKID.

Corrective Action: COMPLY WITH RULE 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. THIS IS THE SECOND NOTICE IMMEDIATE ACTION IS REQUIRED.

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
THIS IS A FOLLOW UP TO INSP. DOC #695105799, THE CA FOR IMPACTED SOIL AROUND WELLHEAD HAS BEEN ADDRESSED. THE CORRECTIVE ACTION FOR OILY WASTE IN PRIME MOVER SKID HAS NOT BEEN ADDRESSED OR THE LEAK IN THE EQUIPMENT HAS NOT BEEN REPAIRED. THIS IS THE SECOND NOTICE FOR THIS CA, IMMEDIATE ACTION IS REQUIRED.	beardslt	05/17/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695106294	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5756988