

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403054499

Date Received:

05/19/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10758

Name of Operator: OGRIS OPERATING LLC

Address: PO BOX 53467

City: MIDLAND State: TX Zip: 79710

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
ATWATER, BONNIE	432-755-0212	batwater@ogrisop.com
BACA, DAVID	719-859-4066	dbaca@ogrisop.com
WARD, GIENA	719-220-4041	gward@ogrisop.com
O'SHIELDS, CHARLIE	940-682-5030	coshields@ogrisop.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 695106011

Inspection Date: 04/06/2022

FIR Submit Date: 04/07/2022

FIR Status: _____

Inspected Operator Information:

Company Name: OGRIS OPERATING LLC

Company Number: 10758

Address: PO BOX 53467

City: MIDLAND State: TX Zip: 79710

LOCATION - Location ID: 309552

Location Name: APACHE CANYON Number: 09-02 County: LAS ANIMAS

Qtrqtr: NWNE Sec: 9 Twp: 34S Range: 67W Meridian: 6

Latitude: 37.104654 Longitude: -104.890861

FACILITY - API Number: 05-071-00 Facility ID: 299644

Facility Name: APACHE CANYON Number: 09-02

Qtrqtr: NWNE Sec: 9 Twp: 34S Range: 67W Meridian: 6

Latitude: 37.104654 Longitude: -104.890861

CORRECTIVE ACTIONS:

1 CA# 160768

Corrective Action: REPLACE OR REPAIR AND POST SIGN WITH 911 AS EMERGENCY CONTACT. INCLUDE API #. CA DATE IS 24 HOURS TO POST 911 AND 5-6-2022 TO REPLACE SIGN AND INCLUDE API#.

Date: 05/06/2022

Response: CA COMPLETED

Date of Completion: 04/22/2022

Operator Comment: THE NEW LOCATION SIGN WAS POSTED ON THE DOOR OF THE SEPARATOR HOUSE ON 4/22/22. THE EMERGENCY CONTACT INFO WAS TEMPORARILY POSTED ON THE SEPERATOR HOUSE WITHIN 24HRS OF NOTICE.

COGCC Decision: _____

COGCC Representative: _____

2 CA# 160769

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,,(2).D.

Date: 04/12/2022

Response: CA COMPLETED

Date of Completion: 04/12/2022

Operator Comment: THE OILY WATER AND IMPACTED SOIL NEAR THE COMPRESSOR WAS CLEANED UP AND REMOVED FROM LOCATION. MAINTENANCE HAS BEEN PERFORMED AND THE SELF INSPECTION PROCESS HAS BEEN REVIEWED.

COGCC Decision: _____

COGCC Representative: _____

3 CA# 160770

Corrective Action: Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2). CA DATE 4-18-2022.

Date: 04/18/2022

Response: CA COMPLETED

Date of Completion: 04/18/2022

Operator Comment: THE BRADENHEAD HAS BEEN MADE ACCESSABLE TO ALLOW VISUAL INSPECTION.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: ALL CORRECTIVE ACTIONS HAVE BEEN ADDRESSED. SEE ATTACHED PHOTO LOG FOR DETAILS.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: GIENA WARD

Signed: _____

Title: SR. ENVIRONMENTAL TECH.

Date: 5/19/2022 11:31:17 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
-----------------	-------------

403054517	PHOTO LOG
-----------	-----------

Total Attach: 1 Files