

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/17/2022

Submitted Date:

05/20/2022

Document Number:

690202934

FIELD INSPECTION FORM

Loc ID 429843 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10762
Name of Operator: JWC OPERATING LLC
Address: 50450 CR 23
City: LIMON State: CO Zip: 80828

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 4 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
CRAIG BILL		jwcranch@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
429842	WELL	SI	02/01/2022	OW	073-06477	JOHN CRAIG 6-2	RI
435536	TANK BATTERY	AC	08/07/2012		-	JOHN CRAIG 6-2	RI

General Comment:

[This is a location and stormwater management inspection.](#)
[See attached photos and additional details within this report.](#)

Location

Lease Road:			
	Type Access		
comment:	There is an unnecessary road being used to access the the battery location. Vehicles shall not travel outside original access road boundary causing additional disturbance.		
Corrective Action:	Comply with Rule 1002.e. Restrict vehicle access to designated access road only.	Date:	05/27/2022

Overall Good:

Signs/Marker:			
	Type BATTERY		
Comment:	The sign at the battery does not reflect current Operator. There is no sign located at the wellhead.		
Corrective Action:	Install sign to comply with Rule 605.	Date:	06/20/2022

Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:			
Yes/No			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:			Date:

Flaring:			
Type			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:			Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Fail			

Comment: There is an area along the access road where stormwater is pooling on the road causing vehicles to drive around and widen the road. There are culverts along the road that are not maintained.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 06/20/2022

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690202935	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5758854