

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:	Adequate		Date:	
Corrective Action:			Date:	

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil around the well needs to be removed. See attached photo		
Corrective Action:	"Properly dispose of oily waste in accordance with 905.e."		Date: 05/27/2022
Type	UNUSED EQUIPMENT		
Comment:	Unused Equipment around the well needs to be removed for good housekeeping. See attached photo		
Corrective Action:	Comply with Rule 606		Date: 05/27/2022

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Panel		
Corrective Action:			Date:

Equipment:

Type: Bradenhead	# 1		corrective date
Comment:	Appears to be plumbed to surface.		
Corrective Action:			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 301330 Type: WELL API Number: 123-30003 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: T/A

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 03/24/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Monday 5/16/22 at approximately 1037hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Abbey D01-23 of Chevron, at API # 05-123-30003 in Weld County, Colorado. During this inspection the following possible compliance issues were observed: Unused Equipment around the well needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 5/27/22 Stained soil around the well needs to be removed. "Properly dispose of oily waste in accordance with 905.e." With a corrective action date of 5/27/22 See attached photos. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	burnsa	05/18/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403053599	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5757247
699105423	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5757241