

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/17/2022

Submitted Date:

05/18/2022

Document Number:

702500045**FIELD INSPECTION FORM**Loc ID 333388 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 56680Name of Operator: MERRION OIL & GAS CORPAddress: 610 REILLY AVENUECity: FARMINGTON State: NM Zip: 87401**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**13 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Thompson, Philana		pthompson@merrion.bz	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214096	WELL	PR	12/01/2020	GW	067-05403	B E BEHRMANN 1	PR

**General Comment:**

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

**Location**Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	There are two NFPA sigs with conflicting information (IMG 08).		
Corrective Action:	Remove or update sign per rule 605.		Date: 07/20/2022

Emergency Contact Number:

Comment:	Emergency contact is listed on sign at wellhead.		
Corrective Action:			Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Bradenhead	# 1		
Comment:	Bradenhead is accessible.		
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:	Horizontal separator is covered with flat screen.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Telemetry		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 3		
Comment:	2" line from wellhead to separator. 2" line from separator to meter house. 2" line from separator to produced water tank.		
Corrective Action:			Date:
Type: Other	# 3		
Comment:	2 4" risers with valves and 1 2" riser with valve.		

Corrective Action:		Date:	
--------------------	--	-------	--

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLs	PBV STEEL		37.100714,-107.592510	

Comment: Partially buried produced water tank covered by steel grating.

Corrective Action:		Date:	
--------------------	--	-------	--

**Paint**

Condition	Adequate	
Other (Content)	Produced Water	
Other (Capacity)	95 bbls	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Inadequate	Walls Insufficient	Base Sufficient	Adequate	

Comment: Weeds beginning to encroach on earth berms (IMG 13). Berm height does not appear sufficient (IMG 07).

Corrective Action: Confirm adequate berm height. Raise and maintain berm if necessary per rule 912.d(1)

Date: 06/09/2022

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No observed impact of storm water. Storm water controls seem sufficient at time of report.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<a href="#">Cone screens over separator vent stack, although not required, are Best Management Practice for wildlife. All other wildlife management appears sufficient at time of report.</a>	klinka	05/17/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403053535	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5757134">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5757134</a>
702500047	Photo document	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5757131">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5757131</a>