

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/17/2022

Submitted Date:

05/20/2022

Document Number:

690202934

FIELD INSPECTION FORMLoc ID 429843 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10762

Name of Operator: JWC OPERATING LLC

Address: 50450 CR 23

City: LIMON State: CO Zip: 80828

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

4 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
CRAIG BILL		jwcranch@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
429842	WELL	SI	02/01/2022	OW	073-06477	JOHN CRAIG 6-2	RI
435536	TANK BATTERY	AC	08/07/2012		-	JOHN CRAIG 6-2	RI

General Comment:

This is a location and stormwater management inspection.
See attached photos and additional details within this report.

Location**Lease Road:**

Type	Access		
comment:	There is an additional road being used to access the the battery location. This road was determined to be in use by the landowner for cattle operations.		
Corrective ActionL		Date:	

Overall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:	The sign at the battery does not reflect current Operator. There is no sign located at the wellhead.		
Corrective Action:	Install sign to comply with Rule 605.	Date:	06/20/2022

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Fail			

Comment: There is an area along the access road where stormwater is pooling on the road causing vehicles to drive around and widen the road. There are culverts along the road that are not maintained.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 06/20/2022

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403055283	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5758855
690202935	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5758854