

Location

Overall Good:

Signs/Marker:

Type	DRILLING/RECOMP		
Comment:	Drilling Rig Sign NOT at First Point of Intersection of a Public Road and the Rig Access Road; See photos		
Corrective Action:	Install signs to comply with Rule 605.c.(1)-(3)	Date:	05/27/2022

Emergency Contact Number:

Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:	<input type="text"/>		
Corrective Action:		Date:	<input type="text"/>

Flaring:

Type		
Comment:	<input type="text"/>	
Corrective Action:		Date: <input type="text"/>

Inspected Facilities

Facility ID: 478239 Type: LOCATION API Number: - Status: AC Insp. Status: AC

Well Drilling

Rig: Rig Name: Ensign Pusher/Rig Manager: _____
 Permit Posted: SATISFACTORY Access Sign: ACTION REQUIRED

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
 Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids

Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____
 Multi-Well: _____ Disposal Location: _____

Comment: _____

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
Routine Field Inspection. Drilling Rig Sign NOT at First Point of Intersection of a Public Road and the Rig Access Road; See photos. Install signs to comply with Rule 605.c.(1)-(3). Corrective Action Date 05.27.2022	petrie	05/25/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403059520	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5763115
696304224	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5763114