

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403071908

Date Received:

06/08/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Bittner, Dawn

stephaniebittner@chevron.com

Olson, Andrew

AndrewOlson@chevron.com

Puechner, Rachel

RPuechner@chevron.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 702800185

Inspection Date: 05/06/2022

FIR Submit Date: 05/10/2022

FIR Status: _____

Inspected Operator Information:

Company Name: CHEVRON USA INC

Company Number: 16700

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

LOCATION - Location ID: 314500

Location Name: WILSON CREEK UNIT-63N94W Number: 35SWSW County: _____

Qtrqtr: SWS Sec: 35 Twp: 3N Range: 94W Meridian: 6

Latitude: 40.181431 Longitude: -107.913732

FACILITY - API Number: 05-103-00 Facility ID: 314500

Facility Name: WILSON CREEK UNIT-63N94W Number: 35SWSW

Qtrqtr: SWS Sec: 35 Twp: 3N Range: 94W Meridian: 6

Latitude: 40.181431 Longitude: -107.913732

CORRECTIVE ACTIONS:

1 CA# 161727

Corrective Action: Install or repair wildlife protection equipment.

Date: 05/15/2022

Response: CA COMPLETED

Date of Completion: 05/25/2022

Operator Comment: The chemical tank and containment BMP were removed from location. Picture is attached. In the picture, the rig moved a trailer on location and the chemical tote was located where the front leg of the trailer is sitting. If a clean picture of the tote site is needed, it can be retaken when the trailer is moved.

COGCC Decision: _____

COGCC
Representative:

2 CA# 161728

Corrective Action: Install or repair required BMPs per Rule 1002.f. Continue to monitor and manage stormwater on the Location. Ongoing stormwater management is required until the site receives a passing final inspection.

Date: 06/09/2022

Response: CA COMPLETED

Date of Completion: 05/25/2022

Operator
Comment:

Wattles were installed to Location per Rule 1002.f. Picture is attached.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been completed

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Dawn Bittner

Signed: _____

Title: Administrative Assistant

Date: 6/8/2022 12:51:30 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403071995	Picture of CA
403071997	Picture of CA

Total Attach: 2 Files