

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/10/2022

Submitted Date:

06/13/2022

Document Number:

690203035

FIELD INSPECTION FORM

Loc ID 308487 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10705
Name of Operator: EVERGREEN NATURAL RESOURCES LLC
Address: 1875 LAWRENCE ST STE 1150
City: DENVER State: CO Zip: 80202

Findings:

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Inspections, Evergreen		cogcc.evergreen@enrllc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272827	WELL	PR	09/22/2004	GW	071-08113	CHATEAU 34-14	RI
278519	PIT	AC	06/24/2005		-	CHATEAU 34-14 ONSITE	AC

General Comment:

[This is a follow up of the previous inspection #690202787.](#)
[See attached photos and additional details within this report.](#)

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: The area of erosion at the culvert along the main road has been repaired and stabilized with rock rip/rap. Areas of disturbance were seeded and hydromulched. Previous corrective action completed.

Corrective Action: Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 278519 Lat: 37.079175 Long: -104.637972

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action Date: _____

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment:

Corrective Action Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment: The pit is not constructed to allow 2 ft. of freeboard due to shallow depth of pit. Previous corrective action has not been completed. Corrective action needs to be performed immediayely.

Corrective Action Comply with Rule 909.c. Date: 11/13/2021

Attached Documents

You can go to COGCC Images (<https://ogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403077514	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5778291
690203036	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5778289