

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/06/2022

Submitted Date:

07/06/2022

Document Number:

699105656**FIELD INSPECTION FORM**Loc ID 310851 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 2001 16TH STREET SUITE 900City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
297393	WELL	TA	02/01/2022	OW	123-27115	FRONT RANGE D 09-28	TA

**General Comment:**

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Access road is overgrown in vegetation. See attached photo.			
Corrective Action	Repair and maintain lease road to comply with rule 204.			Date: 07/15/2022
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Adequate			Date:
Corrective Action:				Date:
<b>Good Housekeeping:</b>				
Type	OTHER			
Comment:	Stained soil next to the well needs to be removed. See attached photo.			
Corrective Action:	"Properly dispose of oily waste in accordance with 905.e."			Date: 07/15/2022
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	WELLHEAD			
Comment:	Panel			
Corrective Action:				Date:
<b>Equipment:</b>				
Type: Bradenhead	# 1			corrective date
Comment:	Appears to be plumbed to surface			
Corrective Action:				Date:
<b>Venting:</b>				
Yes/No	NO			
Comment:				
Corrective Action:				Date:
<b>Flaring:</b>				
Type				
Comment:				
Corrective Action:				Date:



**Inspected Facilities**Facility ID: 297393 Type: WELL API Number: 123-27115 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: T/A

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**Date of Last Brhd Test: 04/14/2022Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0

Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 7/6/22 at approximately 920hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Front Range D09-28 of Chevron, at API # 05-123-27115 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Access road is overgrown in vegetation. Repair and maintain lease road to comply with rule 204. With a corrective action date of 7/15/22</p> <p>Stained soil next to the well needs to be removed. "Properly dispose of oily waste in accordance with 905.e." With a corrective action date of 7/15/22</p> <p>See attached photos.</p> <p>Submit pictures on FIRR.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	burnsa	07/06/2022

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699105657	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5796744">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5796744</a>