



FORM
6
Rev
11/20

State of Colorado
Oil and Gas Conservation Commission
1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DEETOEES

Document Number:

403097938

Date Received:

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number:100322Contact Name:JACQUELINE BUCZEK

Name of Operator:NOBLE ENERGY INCPhone:(720) 771-4366

Address:2001 16TH STREET SUITE 900Fax:

City:DENVERState:COZip:80202Email:JACQUELINEBUCZEK@CHEVRON.COM

For "Intent" 24 hour notice required,Name:Revas, RobbieTel:(720) 661-7242

COGCC contact:Email:robbie.revas@state.co.us

Type of Well Abandonment Report:☒ Notice of Intent to Abandon☐ Subsequent Report of Abandonment

API Number05-123-15884-00

Well Name:UPRCWell Number:7-10Q

Location:QtrQtr:NWSESection:7Township:2NRange:64WMeridian:6

County:WELDFederal, Indian or State Lease Number:

Field Name:WATTENBERGField Number:90750

Only Complete the Following Background Information for Intent to Abandon

Latitude:40.149240Longitude:-104.590570

GPS Data:GPS Quality Value:3.4Type of GPS Quality Value:PDOPDate of Measurement:06/26/2006

Reason for Abandonment:☐ Dry☒ Production Sub-economic☐ Mechanical Problems

☐ Other

Casing to be pulled:☒ Yes☐ NoEstimated Depth:1016

Fish in Hole:☐ Yes☒ NoIf yes, explain details below

Wellbore has Uncemented Casing leaks:☐ Yes☒ NoIf yes, explain details below

Details:

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
J SAND	7541	7574			

Total: 1 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status
SURF	12+1/4	8+5/8	J-55	24	11	827	585	827	11	VISU
1ST	7+7/8	4+1/2	N-80	11.6	11	7924	380	7924	5793	CBL

Date Run: 7/7/2022 Doc [#403097938] Well Name: UPRC 7-10Q

Page 1 of 3

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 7491 with 2 sacks cmt on top. CIBP #2: Depth 6753 with 2 sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 35 sks cmt from 2500 ft. to 2000 ft. Plug Type: CASING Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Perforate and squeeze at 2500 ft. with 155 sacks. Leave at least 100 ft. in casing 2400 CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set 115 sacks half in. half out surface casing from 1016 ft. to 716 ft. Plug Tagged: ☐

Set 225 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☐ No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing

Surface Plug Setting Date: _____ Cut and Cap Date: _____ Number of Days from Setting Surface Plug to Capping or Sealing the Well: _____

*Wireline Contractor: _____

*Cementing Contractor: _____

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes ☐ No

Technical Detail/Comments:

3rd party wildlife surveys will be conducted on this well prior to rigging up for P&A activities.
Notification will be given to any adjacent building unit occupants within a 1000 feet of the wellhead of planned P&A start date.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____

Print Name: ANGELA FIORE

Title: OPS TECH

Date: _____

Email: ANGELA.FIORE@CHEVRON.COM

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____

Date: _____

CONDITIONS OF APPROVAL, IF ANY: _____

Expiration Date: _____

COA Type

Description

--	--

Attachment List

Att Doc Num

Name

403099119	PROPOSED PLUGGING PROCEDURE
403099121	WELLBORE DIAGRAM

Total Attach: 2 Files

General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)