

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403099326

Date Received:  
07/07/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10464  
Name of Operator: CATAMOUNT ENERGY PARTNERS LLC  
Address: 1001 17TH STREET STE 1160  
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
General		Inspections@catamountep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 702500119  
Inspection Date: 06/24/2022 FIR Submit Date: 06/27/2022 FIR Status:

Inspected Operator Information:

Company Name: CATAMOUNT ENERGY PARTNERS LLC Company Number: 10464  
Address: 1001 17TH STREET STE 1160  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 436009

Location Name: Campbell 33-7-4 Number: 1H County: LA PLATA  
Qtrqr: SWS Sec: 3 Twp: 33N Range: 7W Meridian: N  
W  
Latitude: 37.128270 Longitude: -107.600930

FACILITY - API Number: 05-067-00 Facility ID: 436011

Facility Name: Campbell 33-7-4 Number: 2H  
Qtrqr: SWS Sec: 3 Twp: 33N Range: 7W Meridian: N  
W  
Latitude: 37.128270 Longitude: -107.600930

CORRECTIVE ACTIONS:

1 CA# 162923

Corrective Action: Install proper guy line markers per Rule 1003.a Date: 07/09/2022

Response: CA COMPLETED Date of Completion: 07/06/2022

Operator Comment: All rig anchors removed.

COGCC Decision:

COGCC  
Representative:

2 CA# 162924

Corrective Action: Use or remove unused equipment/debris per rule 606.

Date: 07/09/2022

Response: CA COMPLETED

Date of Completion: 07/06/2022

Operator Comment: 2" pump line & temporary fencing from Campbell 33-7-4#2H wellhead to separator removed. 2" pipe on north side of tank containment removed. Tubing rotator on Campbell 33-7-4#1H removed. Water filters removed from location.

COGCC Decision:

COGCC  
Representative:

3 CA# 162925

Corrective Action: Repair required BMPs per Rule 1002.f.(2)C

Date: 07/09/2022

Response: CA COMPLETED

Date of Completion: 07/06/2022

Operator Comment: Wattles in disrepair surrounding location have been cleaned, replaced, and/or reset. Areas near wattles raked and hand reseeded.

COGCC Decision:

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Nolan Redmond

Signed:

Title: Geo/Eng Tech

Date: 7/7/2022 3:13:42 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
-----------------	-------------

403099337	Remedial Report
-----------	-----------------

Total Attach: 1 Files