



STATE OF COLORADO
OIL AND GAS CONSERVATION COMMISSION

DEPARTMENT OF NATURAL RESOURCES
SUITE 380 LOGAN TOWER BUILDING
1580 LOGAN STREET
DENVER, COLORADO 80203

WILLIAM R. SMITH
Director
DENNIS R. BICKNELL
Deputy Director

(303) 894-2100

ROY ROMER
Governor

May 15, 1990

Three States Well Service INC.
RT. 4, 17566 Road 30
Sterling, Colorado 80751

Lease Claycomb 2
Field Big Bend
County Adams
Location SWNE 2-3S-61W

Gentlemen:

An inspection was made of the lease(s) shown above. The following conditions were observed to exist at the time of the inspection.

- ☐ Oil accumulation on the water in the retaining pit
- ☒ Skim pit in need of repairs
- ☒ Covered skim pit or tank required
- ☒ Tank identification number missing or incorrect
- ☒ Wellhead sign required per rule 210(a)
- ☐ Oil spilled at wellhead or tank battery
- ☐ Weeds, debris or waste material observed at site

REMARKS:

The above condition(s) should be corrected immediately. Any surface accumulation of oil in the retaining pits must be cleaned within ten (10) days after receipt of this notice (Rule 328), and a report submitted to this office within thirty (30) days after the work was accomplished, advising us of the date and manner in which the correction was made. Any person who fails to comply with this request is subject to the penalties as provided for under statute 34-5-121 of the Oil and Gas Conservation Act.

E.B. Binkley
Petroleum Engineer

5-5-90
Date of Inspection
0081b/0090b/p 48