

# Construction and Stormwater Inspection

July 26, 2022

Operator: VERDAD RESOURCES LLC #10651

Location ID: 466345

Inspection Document #: 697504073

Weld County, CO

NWNW Section 35 T9N R60W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Boydston /3535  
Location ID: 466345



**Photo 1.** Photo taken from the northeastern location, facing North. Photo illustrates sediment discharge from location. Operator failed to install sufficient stormwater BMPs to comply with Rule 1002.f.



**Photo 2.** Photo taken from the northeastern location, facing West. Photo illustrates gully erosion along the ditch BMP. Operator has failed to properly stabilize the ditch BMP to prevent erosion. Also, the fill slope has only been temporarily stabilized with equipment tracking.

Inspection Photos  
Location Name: Boydston /3535  
Location ID: 466345



**Photo 3.** Photo taken from the western side of the topsoil stockpile, facing North. Photo illustrates the topsoil stockpile has only been temporarily stabilized with equipment tracking and erosion is starting to occur.



Inspection Photos  
Location Name: Boydston /3535  
Location ID: 466345



**Photo 4.** Photo taken from the southern topsoil stockpile, facing Southeast. See comments under Photo 3.



**Photo 5.** Photo taken from the southern topsoil stockpile, facing East. See comments under Photo 3.

Inspection Photos  
Location Name: Boydston /3535  
Location ID: 466345



**Photo 6.** Photo taken from the southern location, facing Southwest. Photo illustrates trash and debris blowing off location. Operator shall collect all trash and debris that has blown off location.