

### Spill Report

<b>Production foreman</b>	Kelly Sharp / 970-630-6880 / Kelly.sharp@ownresoures.com
<b>Date Discovered</b>	7/28/2022 @ 9:00am
<b>Well Name or location</b>	Keller Cattle co. 24-14
<b>GPS</b>	39.87704 / -102.498646
<b>Spill Volume</b>	8 to 10 BBL
<b>Consider All Spills reportable</b>	
<b>Cause of spill</b>	burst plot at transition
<b>How was it contained</b>	Segment was isolated and vac truck pulled water from line and ground
<b>landowner contacted</b>	Yes / Wade Keller / 970 630 4571
<b>Distance from Livestock</b>	same pasture
<b>Distace to buildings</b>	1 mile
<b>COGCC contact person</b>	Rob Young
<b>Comments/ Additional info</b>	After the sement was isolated and water was vac'ed we then replace the transition. Once the line was repaired and backfilled we spread 4 - 50lbs bags of gypspum and also put down and spreem 2 bales of straw.











